Message

From: Beslow, Mike [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=B5DD587C0E294AC3898958FEF9062D03-MBESLOW]

Sent: 2/8/2017 3:08:00 PM

To: Benoit, Simonne T [Simonne.Benoit@arcelormittal.com]

CC: Fitzgerald, Sean F MST1 [Sean.F.Fitzgerald@uscg.mil]; Barnett, Thomas R [Thomas.Barnett@arcelormittal.com]

Subject: RE: ArcelorMittal Indiana Harbor West - inital FTIR analysis reports

My apologies, it is a little confusing as to the locations each sample was taken – could you break down more specifically where each was taken from? (including the mineral oil)

From: Benoit, Simonne T [mailto:Simonne.Benoit@arcelormittal.com]

Sent: Wednesday, February 08, 2017 8:44 AM **To:** Beslow, Mike
beslow.mike@epa.gov>

Cc: Fitzgerald, Sean F MST1 <Sean.F.Fitzgerald@uscg.mil>; Barnett, Thomas R <Thomas.Barnett@arcelormittal.com>

Subject: RE: ArcelorMittal Indiana Harbor West - inital FTIR analysis reports

Mike,

There is a high degree of match between the three samples.

Simonne T. Benoit | Environmental Engineer ArcelorMittal Indiana Harbor LLC | ArcelorMittal USA LLC

MEU Environmental | 3001 Dickey Road, Sta. 001 East Chicago, IN 46312

T +219 399 2109 | F +219 399 3211 | M +219 313 5069 | www.arcelormittal.com

From: Beslow, Mike [mailto:beslow.mike@epa.gov]
Sent: Wednesday, February 08, 2017 8:41 AM

To: Benoit, Simonne T

Cc: Fitzgerald, Sean F MST1; Barnett, Thomas R

Subject: Re: ArcelorMittal Indiana Harbor West - inital FTIR analysis reports

Do you feel the material matches or does not match the sediment?

Mike Beslow On-Scene Coordinator US EPA, Region 5

Please excuse any errors in this message as it was sent from a mobile device.

On Feb 8, 2017, at 8:39 AM, Benoit, Simonne T <Simonne.Benoit@arcelormittal.com> wrote:

Sean & Mike,

Attached please find a copy of Microbac laboratories FTIR analysis of oil samples collected from the boom at the discharge of Outfall 009/010 on Tuesday, January 10th and Friday, January 20th. The FTIRs for these two samples have been compared to the sediment sample collected by USEPA on Friday, January 13th from the South side of the ArcelorMittal Railroad lift bridge (USEPA provided us with a split

of this sample). Also included is a copy of an internal memo which provides our interpretation of these results

Simonne T. Benoit | Environmental Engineer ArcelorMittal Indiana Harbor LLC | ArcelorMittal USA LLC

MEU Environmental | 3001 Dickey Road, Sta. 001 East Chicago, IN 46312

T+219 399 2109 | F+219 399 3211 | M+219 313 5069 | www.arcelormittal.com

<17A0572 1 Bol Doc report 520 01 25 2017 1619.pdf>

<IHWSheeninvestigationmemo262017.doc>